



Algas-SDI™

...Innovative liquid vaporizing and gas mixing solutions

ISO 9001
Certified

Engineering Bulletin


Direct Fired LP-Gas Vaporizer, 40/40H & 80/40H

Bulletin Number: DF 10/03

Main gas lock-in with Robertshaw thermostatic gas valves

Problem: Pilot ignites ok but will not stay engaged once the override button is released.

Resolution: Remove plastic zip tie connected to tag that is located at base of safety interlock override button. This zip tie will prevent the override button from being depressed far enough to allow proper lock-in.



This tag has been relocated on units manufactured after September 2003.

At Algas-SDI we are committed to continuous improvement and customer satisfaction. If you have any questions regarding this bulletin or have an improvement suggestion you would like to make, please write or phone Customer Service.

1140 NW 46 Street, Seattle, Washington, USA 98107
Tel: 206-789-5410 Fax: 206-789-5414 Web: www.algas-sdi.com